



2009225

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. UTR 000 000 661		Manifest Document No. 040521		2. Page 1 of 1							
3. Generator's Name and Mailing Address USEPA REGION 8 999 18TH ST. SUITE 300 DENVER, CO. 80202-2466													
4. Generator's Phone (303) 312-6983				ATTN: FLOYD NICHOLS									
5. Transporter 1 Company Name MP ENVIRONMENTAL		6. US EPA ID Number CAT 000 624 247		A. State Transporter's ID N/A		B. Transporter 1 Phone 877-800-5111							
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone							
9. Designated Facility Name and Site Address CLEAN HARBORS GRASSY MOUNTAIN FACILITY 3 MILE EAST TWIMLES NORTH OF EXIT 41 OFF I-80 CLIVE, UT 84043				10. US EPA ID Number UTD 991 301 748		E. State Facility's ID							
				F. Facility's Phone 801 323-8100									
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity							
				No. Type		14. Unit Wt./Vol.							
a. 'RD' ASBESTOS, 9, NA 2212, PG III				001 CM		00025 CY							
b.													
c.													
d.													
G. Additional Descriptions for Materials Listed Above 11A) CH-656348 25 YD. ROLL OFF (SALES ORDER # D9789570) (ASBESTOS CONTAMINATED PPE + DEBRIS DOUBLE BAGGED + WETTED)				H. Handling Codes for Wastes Listed Above									
				<table border="1"> <tr> <td>CR</td> <td>✓</td> </tr> <tr> <td>FS</td> <td>✓</td> </tr> <tr> <td>OFFC</td> <td></td> </tr> </table>				CR	✓	FS	✓	OFFC	
CR	✓												
FS	✓												
OFFC													
15. Special Handling Instructions and Additional Information USE STANDARD PROTECTIVE CLOTHING + EQUIPMENT.													
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.													
Printed/Typed Name Floyd D. Nichols OSC				Signature Floyd D. Nichols		Date 5/21/04							
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature Kelly Young		Date 05/21/04							
Printed/Typed Name Kelly Young				Signature Kelly Young		Date 05/21/04							
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date							
Printed/Typed Name				Signature		Date							
19. Discrepancy Indication Space													
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.													
Printed/Typed Name Wendy Riddle				Signature Wendy Riddle		Date 05/24/04							



NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

LOAD SUMMARY RECORD

GM 5123

LOAD DISPOSAL DESTINATION						
<input type="checkbox"/> STABILIZATION	<input checked="" type="checkbox"/> RCRA CELL 7	<input type="checkbox"/> TSCA CELL	<input type="checkbox"/> SPOT STABILIZATION			
LOAD TRACKING INFORMATION						
PLANT RECEIVED	DROPPED	FINAL CODE	REVIEWED	WEIGHTS	GRIDS	MANIFEST MAILED
		5/24		W	W	
DATE			LOAD NO.			
5-24-04			2004062067			
GENERATOR			HAULER			
USEPA Reg 8			MP			
ORDER NO.			DRUM NO.			
D9789570			5315788			
TRUCK NO.		CONTAINER NO. (s)/ RAILCAR NO.				
578		MP - 4978				
CONTAINER TYPE:				LOAD COUNT (RAIL ONLY):		
ED (G) TT FB V OTHER				1 2 3 4		
OPERATOR SIGNATURE				COUNT		DATE

7:33 AM 05 24 04
44200 lb

8:48 05 24 04
44200 lb (H)
41660 lb TARE
2540 lb NET

LOAD WASHOUT INFORMATION			WASHOUT STAMP	
WASHOUT: TYPE:				
YES NO INTERIOR EXTERIOR				
WASHOUT SIGNATURE		DATE		
DRIVER SIGNATURE		DATE		
		5-24-04		
		5-24-04		

ITEM	COMMENTS	NAME	DATE

Clean Harbors Grassy Mountain Facility, Tooele County, Utah